## **Edit Point Descriptions in GNSS Solutions**

Make sure the Set Feature Codes is enabled by clicking on *Tools* in the menu bar and selecting *Preferences* from the drop down menu.



Check the box next to Show CAD functions.



Click on the *Points* tab in the workbook to view the point list with the descriptions. *Select one or more points to edit by clicking on the line number to the left of the point name*. Use the shift and ctrl keys for multi-point selections.

Selected points are highlighted in the workbook and on the Survey View.



Once the point selection is done click *Project* in the menu bar and select *Set Feature Codes* from the drop down menu.

GNS	S Solutions	- [Su	irve	y View.map - ZMax + PM3 12FEB06 -	USA/NAD83/Ca
🚮 File	Edit View	Мар	Proj	ject Tools Window Help	
12 1 🔁 🖬 🝘   🕺			<b>1</b>	Edit Settings	
1		-1	渦	Download Raw Data from Receiver or Card	F3
]]		الند	Ň	Import Raw Data from Files	F4
-			1	Download Raw Data from Internet	
	Pr	oject	Ğ	Import Geo Data from Files	
🖏 Proj	ject Settings			Changes Inte	
92				Change Into	
Create New Project				Merge Points	
🤁 Open Existing Project			×	Define Control Points	1
			?	Blunder Detection	
Cor	itinue "ZMax `	10SEP	721	Rebuild Process Scenario	Suc
	In	nort		Process All Baselines	F5
	Pro	reco	T	Process Unprocessed Baselines	F6 1
Adjustme				Process Ontions	1
Aujusune			×	Clear Process Results	
CAD			102	acti nocess results	
Export			Ń	Adjust Network	F7
Мар			Q	Check Loop Closure	
	Uti	lities	×	Clear Adjustment Results	
1	J		0	Edit Feature Code List	De De
Washbackthi 7May 1 B			1	Set Feature Codes	0
WOIKDO	UK.(DI - 2116		X	Process Feature Codes	100
	Name			Group Points	non
1	W005	XWA		Gloup Formann	
2	W001	XWA	<b></b>	Upload Positions to External Device	
3	W002	XWA	٢	Export Geo Data to File	F8
4	W003	XWA		Land Survey Report	F9
5	W004	XWA	1		
6	PS02	PK		Compute Datum Shifts	
	<b>Fie</b>	SVE		Coordinate Calibration	ors
× Feat	ure code	appl:	_	Compute Ground System	F
Applying Feature (			17	Import Vector Map	
Feature code appl:			1	Import Raster Map	
				Upload Maps to External Device	
		) /	1/5	542 💽 🗙 🔪 ZMax +	PM3 12FEB06: 🔻

Cat calacted paints fastura cades

The Set Feature Code box will appear. *Type the new feature code in the data entry field* (or select it from the drop down by clicking on the arrow to the right). Click on *OK*. Choose To Apply or To Apply and Process. (Reference Chapter 12 in the GNSS Solutions manual for more information regarding these options).

In this example the objective is to modify the description, therefore choose *To Apply*.



The point descriptions for the selected points now have the edited values.

GNSS Solutions - [Survey View.map - ZMax + PM3 12FEB06 - USA/NAD83/California (Zone3) NAVD88												
🕅 File Edit View Table Project Tools Window Help												
<sup>™</sup>   🔁 🖬 🕼   X 📭 🛍   X + Q +   📧 💌   🔗 🕲												
Project						WOOS BJSS0150000000						
🎦 Create New Project				X								
🔁 Ope	en Existing Proj	ject	1954000.0		H	W002	1					
🔁 Cor	ntinue "ZMax 1	0SEP05"	2		11000		1					
	Im	port	-			W001	۲					
Process							-					
	Adiu	stment	1953500.0	o hand		- PLINT	1					
	Ć	AD	<b>b</b>			1919						
	Ex	coort	ПР "		R		È					
	N	1ap					2					
Utilities			MISS	6142000.00		6143000.0	00					
<u> </u>			Survey V	/ie Design Vie	Time Viev	vt	_					
Workbook.tbl - ZMax + PM3 12FEB06 - USA/NAD83/California (Zone3) NAVD88 US ft - US Feet												
	Name	Description	East	North	Ortho height	Status	Τ					
V							T					
1	BASE	MAG	6144657.185	1953603.596	66.487	Adjusted	١					
2	W005	MyCode	6142706.987	1954316.330	67.851	Adjusted	+					
3	PS02	PK	6145001.122	1953626.490	67,100	Adjusted	L					
5	W002	XWALK	6142877.773	1953913.893	71.294	Adjusted	1					
6	W003	XWALK	6143776.689	1953957.368	70.294	Adjusted	1					
✓ ▲ ▶ ▶ Files Points Control Positions Vectors Repeat vectors Loop Closure Control												
							_					

Phil Stevenson February 23, 2006