



Firmware Release Notes

DATE: JULY, 2014
PRODUCT: GNSS SERVICE LAYER FOR MOBILEMAPPER 120, PROMARK 120/220
SUBJECT: NEW GNSS SERVICE LAYER RELEASE
NUMBER: V2.3 (W214He27)

Introduction

This release is a new version of GNSS Service Layer. It is an update of the latest official version of Service Layer V2.2 including bug fixing.

Service Layer V2.3 Platform software is compatible with the following devices:

- MobileMapper 120
- ProMark 120
- ProMark 220

Components

New components are in **bold**

| | Release Version | Version | GNSS |
|--------------------|-----------------|-------------|------|
| Previous version | V2.2 | W213 | Hw26 |
| New version | V2.3 | W214 | He27 |

Upgrading instructions

Copy GNSS ServiceLayerV2.3.CAB file on the receiver unit using Activesync and execute it.

New features/Enhancements

N/A

Resolved problems

- Fixed an issue with SPSO by improving occupation management (problem with start/stop job event) (FNC 64)

Kown issues

N/A