

## Addendum to A12-B12-AC12 Reference Manual Rev E

List of known errors:

1. Message Output Rate 2. Power Pinout

## 1. Message Output Rate

(December 2006)

The output rate for all messages can be set to any value between 1 and **255** seconds, not between 1 and 999 seconds.

This error affects the following pages in the A12-B12-AC12 Reference Manual (P/N 630871E). Please correct them accordingly.

Page 24, 3rd line Page 60, in Table 6-11, in PRTA and PER rows Page 73, 11th line Page 76, last line Page 78, 3rd line from the bottom Page 80, 6th line Page 82, 4th line from the bottom Page 84, 6th line from the bottom Page 89, 7th line Page 91, 4th and 18th lines Page 94, 7th line Page 96, 5th line after Table 6-39 Page 99, 7th line Page 103, 5th line Page 105, 6th line after Table 6-46 Page 107, 5th line after Table 6-48 Page 109, 3rd line Page 117, 4th line from the bottom Page 118, 7th line Page 120. 8th line Page 123, 6th line.

## 2. Power Pinout

(January 2007)

Figure 4-4 on page 36 is inaccurate. Pins 1 and 3 on the power connector should be inverted. Below is the corrected diagram.




Figure 4.4: Connector Pinouts