

**Product Marketing Update**

Document: 650xSK-01E

31 March 2003

**6501/6502 SK****UHF transmitter interface****Product concerned**

Product Names:

**6501 SK; 6502 SK**

Product Family:

**Land survey****1. PROBLEM / ANOMALY**

We had some cases of 6502 SK receivers sent back to factory for repair. Those receivers could not communicate with the external Thales Navigation UHF radio link module. Hence the base station was unable to broadcast corrections.

**2. SOLUTION**

The user must connect all cables, especially the UHF data link module cable, to the 6502 SK receiver before connecting the power source and switching on the receiver.

**3. CUSTOMER NOTIFICATION**

This Product Marketing Update will be distributed to all channels in order that they can provide suitable notices to their customers.