



Firmware Release Notes

Date: April 13, 2012
Product: GNSS Service Layer for ProMark 100/200
Subject: New GNSS Service Layer release
Number: **v1.5.4**

Introduction

This release is a new version of GNSS Service Layer. It is an update of the latest version of Service Layer v1.5.3.

Service Layer v1.5.4 firmware is compatible with the following devices:

- ProMark 100
- ProMark 200

Components

New components are in **bold**

	Release Version	Version	GNSS
Previous version	V1.5.3	W091	Hv23
New version	V 1.5.4	W092	Hv23

Upgrading instructions

To install new GNSS Service Layer on your device, you must establish a Microsoft ActiveSync connection between your PC and the GNSS receiver, copy the GNSS ServiceLayer v1.5.4 CAB file and execute it on the GNSS device. Then follow the instructions.

Languages supported

The following languages are supported with the version 1.5.4:

- Chinese Simplified
- Chinese Traditional
- Japanese
- Korean
- English
- French

- German
- Greek
- Italian
- Portuguese
- Spanish

New features/Enhancements

N/A

Resolved problems/Improvements

This new GNSS Service Layer loads NTRIP source table regardless of its length.

Recommendations

If your GNSS receiver is updated with the Service Layer v1.5.4, and you are using ProMark Field application, make sure that it is updated to v2.0 or further version.