Firmware Release Notes	**Survey**

DATE: JULY 9, 2013
PRODUCT: PROMARK 120 / 220
SUBJECT: NEW GNSS FW RELEASE
NUMBER: V2.2 (W213Hw26)

Introduction

This version is an update of GNSS FW 2.1 including several new features and enhancements and well as bug fixing.

Upgrade procedure

Upgrade procedure:

- Please refer to OS Language and Applications Installation Procedure for exact description of the installation process. This procedure is included into the GNSS FW W213Hw26 and GNSS Toolbox v3.5 installation files.

New features/Enhancements

N/A

Resolved Problems/Improvements

- ProMark 120 required L2 option activation to make it working as a RTCM3 base (only 1006 & 1033 messages were generated).

Known issues

N/A