

# Randy's Rules for RTK

- Make a box and work inside the box
- Make measurements when the PDOP is less than 4
- Use at least six SV's
- Set the data collector for ACCURACY and let the time on point vary with conditions
- Set the accuracy tighter than what you must have for the job
- Stand on the same side of the pole