

## Latest versions of MobileMapper CE firmware and software 8 June 2007

The following are the latest versions (as of April 2007) of MobileMapper CE firmware and software, together with links for downloading them. You may check which versions of firmware is currently installed on your MMCE by tapping Start > Settings > Control Panel > Thales System Info.

1. MMCE operating system (OS) version 2.91

<ftp://ftp.magellangps.com>

Folder: /Mobile Mapping/MM CE/Firmware/

File name: MMCE\_Receiver\_FW.zip

Note: A new MMCE OS version (2.92) was created to support RoHS-compliant MMCE receivers that were introduced in 2007. If your MMCE has washers around the screws holding down the flaps over the external antenna and SD card ports or has a blue PCBA board visible inside the SD card slot, it is RoHS-compliant and must use OS version 2.92. All earlier MMCE receivers must use 2.91 because installing 2.92 in them will render them inoperable. If you have an RoHS-compliant MMCE and need to reinstall OS 2.92, please contact Magellan Professional Tech Support at [professionalsupport@magellangps.com](mailto:professionalsupport@magellangps.com).

2. MMCE GPS firmware version E032

<ftp://ftp.magellangps.com>

Folder: /Mobile Mapping/MM CE/Firmware/

File name: MMCE\_Receiver\_FW.zip

Note: GPS FW version E032 was created to support RoHS-compliant MMCE receivers that were introduced in 2007. E032 is otherwise identical to version E031. If your MMCE has washers around the screws holding down the flaps over the external antenna and SD card ports or has a blue PCBA board visible inside the SD card slot, it is RoHS-compliant and must use GPS FW version E032. All other MMCE receivers may use either E031 or E032.

3. MMCE Eboot version 1.27

Version 1.27 is the latest release but all versions work equally well with most MMCE receivers. Only the splash screens are different. For this reason, we have not posted any Eboot firmware to the tech support ftp site.

Note: A new MMCE Eboot version (1.28) was created to support RoHS-compliant MMCE receivers that were introduced in 2007. If your MMCE has washers around the screws holding down the flaps over the external antenna and SD card ports or has a blue PCBA board visible inside the SD card slot, it is RoHS-compliant and must use Eboot version 1.28. All earlier MMCE receivers must use 1.27 or earlier versions because installing 1.28 in them will render them inoperable. If you have an RoHS-compliant MMCE and need to reinstall Eboot 1.28, please contact Magellan Professional Tech Support at [professionalsupport@magellangps.com](mailto:professionalsupport@magellangps.com).

4. ESRI ArcPad version 7.0.1.53  
<http://www.esri.com/software/arcgis/arcpad/download.html>
5. GPSDifferential for ArcPad version 1.0.0.2  
<ftp://ftp.magellangps.com>  
Folder: /Mobile Mapping/MM CE/Software/GPSDifferential for ArcPad/  
File name: GPSDifferential for ArcPad.zip
6. FAST Survey 2.0.2  
<ftp://ftp.magellangps.com>  
Folder: /Mobile Mapping/MM CE/Software/FAST Survey V2.0.2 for MMCE/
7. Microsoft ActiveSync version 4.5  
<http://www.microsoft.com/downloads/details.aspx?FamilyID=9e641c34-6f7f-404d-a04b-dc09f8141141&DisplayLang=en>
8. MobileMapper Office version 3.40 (Note: this is a software suite for the PC only.)  
<ftp://ftp.magellangps.com>  
Folder: /Mobile Mapping/MM Office/Software/  
File name: MMOffice3\_40.zip