



Date: September 23rd, 2011
Product: U-Link Rx 4W
Subject: U-Link v1.02 Firmware Release

Introduction:

This document is the firmware release note for U-Link v1.0.2.

New features

N/A

Resolved Problems

Solving reception problem (demodulation at -80dBm to -50dBm level).

Known issues

N/A

Recommendations

This firmware should not be upgraded on U-Link Rx modules when working with U-Link repeater.