

## Installing CAD Converter For FAST Survey

Some FAST Survey users may be interested in using the CAD converter provided on the FAST Survey installation CD to convert their jobs into one of the following standard formats: DXF, DWG or DGN.

Installing the CAD converter on your field terminal is a manual procedure, as described in this Application Note.

1. Insert the FAST Survey Installation CD in your office computer.
2. Wait until the FAST Survey V2.6 Installation window opens on the screen.
3. Click on the **Explore the CD** menu. This opens a File Explorer window listing the content of the installation CD.

4. Double-click on the **CADConversion** folder to view the content of this folder (see figure below).
5. Select the two files and copy them to your field terminal via the office computer, using an SD card or a USB connection via ActiveSync. The files should be copied to the **SurvStar** folder (in ../Program Files/FAST Survey/).

FAST Survey will now be able to use this converter whenever necessary: In FAST Survey, you can now tap the Map Icon in the upper right (🌐), then tap **FILE > .dxf/ .dwg/ .dgn** and use these routines: **Import .dwg**, **Export .dwg** and **Import .dgn**.

NOTE: The "cadfileconv2.exe" file will be used to import DGN files.

