

## Product News

Survey / GIS

Document: MKG06-001

09 January 2006



## MobileMapper Beacon now shipping again

### Product concerned

Product Name:

**MobileMapper Beacon**

Product Family:

**Survey / GIS**

### 1. PURPOSE

The power supply and sensitivity issues associated with the MobileMapper Beacon (p/n: 980786) have been resolved and shipping has re-commenced.

### 2. UNITS AFFECTED

The problems resolved have addressed two issues.

One is a power supply issue which manifested itself in overheating batteries. 50 units were affected by this problem have serial numbers 19915-0001 through 19915-0050.

The other issue is reduced antenna sensitivity due to an antenna tuning problem on the production line. Units affected by this problem have date code 0551 or lower.

### 3. CUSTOMER NOTIFICATION

Dealers that have received units with the power supply problem will be contacted directly by us and offered the opportunity of returning their unit for re-tuning at their convenience.