



FAQ: How to run Evaluate

1. Double-click on Eval32.exe
2. Click on OK button to connect to GPS receiver
3. Select the com port the receiver/PC cable is using (COM1, usually)
4. Set Baud to 19,200, 8, none, 1, "User RTS/CTS"
5. Click on OK
6. Click on Connect
7. Click on GPS>Terminal and type in the PASH command you want, e.g.
\$PASHQ, RID
8. When done, click on GPS>Disconnect.