

9 August 2016

Spectra Precision Distributor Confidential

## New Firmware for the Spectra Precision SP80 GNSS Receiver



### SP80 Firmware v3.10

Firmware version 3.10 for the SP80 GNSS receiver is now available together with release notes on the [Spectra Precision website](#) in the *Support* section. The firmware is comprised of new features, improvements and resolved issues. New features include:

- UHF Networking
- WiFi Access Point
- GNSS Updates
- Multi-Language
- Web UI Updates
- Phone number
- USSD protocol
- UHF Relay Mode
- New option for RTX (RAM)

For more details, please see [SP80 v3.10 Release Notes](#).

**This document is for informational purposes only and is not a legally binding agreement or offer.  
Spectra Precision makes no warranties and assumes no obligations or liabilities hereunder.**

**Spectra Precision, 10368 Westmoor Drive, Westminster, CO 80021, USA  
Spectra Precision, Rue Thomas Edison, ZAC de la Fleuriaye – BP 60433, 44474 Carquefou (Nantes), FRANCE**

© 2015, Trimble Navigation Limited. All rights reserved. Spectra Precision is a Division of Trimble Navigation Limited. Spectra Precision and the Spectra Precision logo are trademarks of Trimble Navigation Limited or its subsidiaries. All other trademarks are the property of their respective owners.